QUALITY ASSURANCE REQUIREMENTS (QAR) (CONTINUATION SHEET) (QUALITY ASSURANCE PAM 702-101)

PART II - INSPECTION REQUIREMENTS - (CONTD)

TABLE I - CLASSIFICATION OF QUALITY CONFORMANCE CHARACTERISTICS - (CONTD)

CLASS	CHARACTE	RISTICS		DWG. ZONE	INSPECTIO	ON METHOD	
MAJOR	(CONTD)						
103	VERIFY INTERNAL SPIRAL RETAINING RING IS IN PLACE			C-4	HOLD HOUSING WITH HAND AND PULL AND TURN GEAR. GEAR AND SHAFT MUST NOT COME OUT.		
104	VERIFY PUMP ELEMENT ROTATES WHEN SHAFT IS TURNED				ROTATE PUMP SHAFT AND VERIFY PUMP ELEMENT IS ROTATING BY OBSERVATION FROM PUMP PLATE SIDE		
105	VERIFY PROPER ORIENTATION OF PORT HOLES IN PLATE ASSEMBLY			C-4	VISUAL		
MINOR	A.Q.L. 4.0% DEFECTIVE						
201	IDENTIFICATION MARKINGS (MIL-STD-130)				VISUAL		
i		TABL	E II - 100%	INSPECTION	,		
ROTATE SHALL	FREELY AND BE CAUSE FO PUMP ASSEM CHAR SHAF AND ASSE	HERS AND TO NOT BIND. R REJECTION BLY IS SUBMED ACTERISTIC T SHOULD RO NOT BIND WHEN BLY IS TOR URE PLATE	EVIDENCE O . SUCCESSF ITTED TO GO TATE FREELY EN PUMP	F BINDING C UL COMPLETI VERNMENT FO	R NOT TURNI	NG FREELY IS REQUIRED . E. METHOD	
		Cz.					
QAR	12-17-86	A92-04-14				OAR NUMBER	
REVISION SYMBOL						11629428	
& DATE						PAGE NUMBER 2	
TA FORM 44 NOV.75	452 A-1	PREVIOUS É	DITIONS OF THE	S FORM ARE OBS	ILETE May	11 1987	
~		- Marin Sadan in European Curry gray gray				10	

STA FORM 4452 A-1 1NOV.75

Α